


Lotte Hotel, Korea

Pursanova Ltd, Inc.

December 31, 2004



Water supply pump 10kg/m²



PUR-ST-25DL

The photos on the left clearly show the algae growth and murkiness of the water tank. The photos on the right show the improved clarity of the water after treated with the Pursanova system. The algae is no longer growing on the sides of the tank or in the water. The only indication there was any algae is the stain left on the sides of the tank.

Lotte Hotel Korea water reservoir tank comparison

Photo taken Jan 3rd 2005



Photo taken March 3rd 2005

